MONTHLY **CRASH TEST BOA**

In a new, world-first series, Yachting Monthly creates a wide range of potential disasters to find out if the theories we've all heard actually work in practice

SINKIN (<u>+</u>! 10 ways to fix a hole in the hull at sea

You've hit something and vou're holed. What do you do next? Chris Beeson and the Crash Test crew smash a hole in the hull to test 10 ways of saving a sinking vacht

e were 25 miles north-east of Ramsgate. I was on watch while my son Victor rested in his bunk. At around 0130 I heard a bumping sound, the boat's speed dropped and she was pushed to port. This seemed consistent with the squally southwesterly Force 6-7, but I felt something was wrong. I asked Victor if he'd noticed anything. He said he'd heard a sound like a loud knock on a door. Still unsure what had

The Crash Test Boat team

Chris Beeson, skipper Over 30 years' sailing. 40,000 ocean miles logged including three Fastnet Races, two Transatlantic crossings, and one non-stop Round Britain and Ireland Race. He is the author of the Handbook of Survival at Sea.



Andrew Brook, crew Andrew has sailed for

15 years. He has worked on Mediterranean charter yachts as a sailing instructor and engineer. His two longest passages are Gosport to Corfu in 2008 and Torquay to La Coruña in 2010.



Kieran Flatt, crew A sailor for three decades. Kieran has spent the last 10 years cruising a 28ft sloop around the English Channel, Bay of Biscay, Bristol Channel and Irish Sea. He has also crewed in offshore races and worked as a sailing instructor in the UK and France.



Steve Adams, TV With 20 years in TV production, Steve

now makes videos for his company (www.yachtingtv. co.uk). Subjects include Atlantic and Biscay crossings. A passionate sailor, he is always looking for exciting ways of bringing sailing to life on TV.



many passages around the UK and Europe. Owned many boats, including a classic wooden Vertue sloop.

happened, I checked the bilges and saw to my horror they were full of water. I saw no damage and the keelbolts seemed fine.

Soon the water level was above the floor and, despite bailing with a bucket, it continued to rise, pouring into my boots. I checked the seacocks. If something was wrong with them, I could stop the flow with a wooden plug. But they were OK. There must be damage to the hull itself. I continued bailing and considered pulling a sail around the outside of the

fest methods

The test required repeated 'sinkings' to assess the effectiveness of various repair methods, so we decided to 'sink' the boat using the slings of MDL's Hamble Point Marina travel hoist. We lifted and drained the hull between each test to assess how effective each



method had been. Had we not done this, the hole would soon have been below water, making this difficult. We chose to smash a hole in the hull under the forecabin bunk on the starboard side. To improve access for filming and photography, we removed both heads doors and the pillar between.

This had the benefit of making the hole fairly easy to get at. At sea, it's quite possible that the hole would have straddled and partially destroyed a bulkhead. While

LEFT: We tested with the boat floating in the travel hoist's slings

hull to try and stem the flood. But with a fin keel, it was unlikely I'd get the sail close enough to the hull. I thought of breaking off the cupboards and interior fittings to inspect the hull for damage, but the water was pouring in so fast, there wasn't time...'

This first-hand account of a mystery collision, 25 miles northeast of Ramsgate in 2004, is from Dutch father and son Menko (49) and Victor Poen (13), who took to their liferaft after their 32ft GRP yacht, Laughing Gull III, sank.

What works best?

Whether it's rocks, a floating log, or a shipping container, the chances of being holed below the waterline in a collision are remote. But as they say, accidents happen and worse things happen at sea, so we decided to put to the test various methods to stop a boat from sinking.

The chances are you'll know about a collision the second it happens. Once you've picked yourself up, you will need to heave-to, as the damage is likely to be on the leeward side. Assuming there are two of you aboard, get your crew to prepare the grab bag and liferaft and then



'Even with a small hole, in just seven minutes, we had two tonnes of water inside the hull!'



start using the manual bilge pump in the cockpit. If it's not already working, switch on the automatic bilge pump and send out a DSC alert and a Securité message on the VHF radio. It's important to do this first, before the water level rises enough to short out your batteries. Your hand-held VHF radio's range will be much less.

Next, pull up the sole boards in the main fore-and-aft passage to expose the length of the bilge and check to see if water is flowing in. If it is, make a note of its general direction of flow, or check for changes in boat trim, and you'll have a good place to start. It's likely to be forward.

Empty lockers until you find the hole. If you have clear access, and the hole isn't too big, stuff a cushion over it and hold it in place with your foot. This worked surprisingly well for us as a first response. If access is poor, clear any joinery with a hammer, then use the cushion. Now call your crew, assess the situation and plan your repair.

Visit our website **WWW.yachtingmonthly.com/sinking** to see Yachting TV's video footage of this test

Two-stage testing

First, we explored emergency measures to stop the flood, buy time and regain control. For these, we used kit you would expect to find on an average cruising yacht. Then we tried out some ideas for making good a longer-lasting repair that would have enabled us to sail home – hopefully without continual pumping and bailing.



Clearing plywood joinery is easy, but glassed-in ply bulkheads are much tougher

the bulkhead would be easy enough to clear, the lamination at its joints would not, making any internal repair very tricky. In that instance, an external method of stopping the flood should buy enough time for a longer-term repair below. With the boat in a cradle, yacht repair company Osmotech UK set to work smashing the hole in the hull, which proved amazingly strong! The area inside the hull was first weakened by an angle-grinder, followed by 25 minutes of bashing with a lump-hammer. Finally, we had a hole roughly 8cm (3in) across, around 20cm (8in) below the waterline. The GRP shards were pushed into the boat to simulate collision damage. To drain the

bilge between tests, we drilled two 5cm (2in) holes either side of the keel, through inch-thick laminate, using circular drill bits. During tests, these were plugged from inside with wooden bungs.

The hull's resistance to being whacked with a 12 lb hammer was impressive, but a moving 7-tonne boat striking a rock would result in a quite different outcome. We also knocked out some interior joinery in the forward cabin, to avoid concerns that water would flood only that sector to the waterline, then stop. This also allowed us to better assess how much water was flooding in – and demonstrated how easy it is to smash away interior woodwork to access a hole. Very easy, except for the lamination point at the hull.

The test was as valid as any of this type could be. After a collision, no two holes will be the same. Each will present different challenges but meeting them will require similar methods. We tested many ways to stop water flooding into the hull, some of which only occurred to us on the day. The big surprise was that, even with a small hole, in just seven minutes we had two tonnes of water inside the hull.



Two drainage holes were drilled either side of the keel

Find out if we could stop her sinking



10 'Buy you time' repairs

QUICKEST Cushion stamped against the hole

As the boat was lowered and the water began to gush in, my first reaction was a sudden rush of adrenalin. I grabbed a bright orange cushion, which has always lived in the forepeak of the Crash Test Boat, and held it over the hole with my boot. This took a second and greatly reduced the flow of water. It was a major confidence boost and definitely the quickest quick fix.



It might not look too bad but we took on 2,000 litres of water in just 7-8 minutes



but what's your next move?

Flat plywood board

This involved using a coat hanger to push a loop of line out through the hole, which a crewman on deck snagged with his boathook. He then inserted the line through a pre-drilled bunkboard, knotting the end to hold it in place, before I hauled the board from inside the boat, tight against the outside of the hull. A G-clamp proved



We poked out our hauling line using a straightened coat hanger

invaluable, providing a convenient anchor to tension the lines in this and other methods of stemming the flood. It took a couple of minutes to implement and the results weren't spectacular.





ABOVE: Kieran snagged the hauling line with a boathook and tied on the board. LEFT: Even hauled in tight, this repair leaked quite badly

Flat engine room board A piece of engine room hatch, lined with sound-proofing sponge, was pre-drilled as the Mark II version of the flat plywood board solution. Once again, a loop of line was pushed through the hole, which Kieran, on deck, snagged with a boathook and inserted through the board's pre-drilled hole. It took the same time to deploy, but was much more effective.



LEFT: We could have stamped a cushion over the hole while running the hauling line



LEFT: The hauling line was threaded through the board and fastened with a stopper knot. BELOW: The result was much more effective





Fothering a sail **Tried and trusted** by Admiral Nelson after cannon ball damage, this involved wrapping a sail around the hull, leech forward as it's smoother. It was not quick. Lines needed attaching to each corner, then it needed a boathook to sink the sail under the hull's knuckle. Twists needed to be removed before see-sawing the sail into place and securing very tightly to the toerail. Sadly, due to the sail's built-in camber, it 'pulsed' against the hull, proving a decent fix one second, awful the next.



Fothering a sail took a long time and any sail is fundamentally ill-suited for the job



The sail 'pulsed' against the hull, making a bad repair one minute ...



... and a pretty decent one the next. The result isn't worth the time





It reduced flow significantly but opened up splits around the hole

Lifejacket wrapped in a towel

This idea really appealed to me - fast and ingenious. At least, it might have been, with a bigger, rounder hole. As it was, I needed to stuff the assembly through the hole with an oar, making the hole bigger and the gush of water worse. Once in place, I fired the manual inflator and the flood slowed considerably. However, the inflation did open splits in the hull and water seeped relentlessly through them.



collision mat I tried to get

a purpose-made collision mat, priced at £622 (\$999), from an American company, but they never replied, so I spent £16.99 on a sheet of damp course membrane and £17 on four Strong Grips. If not pre-prepared, it takes five minutes to assemble, longer than the sail. It also needed to be prodded under the hull's knuckle but the flat. smooth material was see-sawed into place more easily than the sail and sat flat on the hull, stopping the torrent of water almost completely. **STRONG GRIPS** Price £8.50 for two Contact **Outboard Covers** Tel 020 8874 3251 Website www. outboardcovers.co.uk



sheet proved a perfect fix



Strong Grips were taped to each corner



but not for us

Umbrella

Always a bit of a long shot, this one, but worth trying if only to challenge the old truism about the two most useless things aboard a yacht being a retired navy officer and an umbrella. This one was a giveaway brolly from a newspaper promotion. I tied a line to the tip (to make sure the umbrella didn't sink into the marina) and then prodded it through the hole. When I tried to open the brolly, the handle fell off inside the hull. Looking at the shreds caused by the splintered GRP, it wouldn't have worked anyway.

How did the Subrella fare? Turn over to see '



Subrella

This is a purpose-made emergency collision 'patch' – a sort of hi-tech 'umbrella'. As before, a line was tied on to prevent loss before it was thrust through the hole. Because of the size of the Subrella and the relatively small hole, it had to be hammered through with the blunt end of an oar. The hole was enlarged as a result but,

once deployed with its safety line secured to the G-clamp, it slowed the flood to a level that would definitely buy you time. Alas, it is no longer in production and the patent belongs to a now defunct company.





The Subrella was too big for our hole and needed forcing through with an oar



The Subrella is no longer made. Production volumes were not high enough to bring down costs



The idea is sound enough, quickly and easily prepared, but how does it work in practice?

Towel in garden refuse bag This idea aimed to exploit external water pressure by forcing a bagged item through the hole so that the water pressure could force it back against the hole, sealing it. Unfortunately, the bag shredded as it was



towel opened the hole

pushed through the jagged hole, leaving the towel prising the hole open and allowing water to gush in. It wasn't an encouraging result and we perhaps overestimated the water pressure.

Sail in sailbag Again, the principle was to push the bag through the hole then stuff the sail into the external part of the bag so the water pressure could push it back onto the hull. Again, the idea overestimated the water pressure and simply forced the GRP shards apart and opened the hole. The ingress can only be estimated from what was flowing out of the bulkhead, but it didn't look at all encouraging.





ABOVE: Another simple idea, but did it work? LEFT: No. Again the sail simply opened up the hole

So you've made a temporary repair, can you effect a more durable one? See over 🚽



5 'Get you home' repairs

aving established that our best quick fix was the DIY collision mat, that was the method we deployed to buy us time while we tested our 'get vou home' repairs. We used an underwater epoxy repair kit designed for the purpose; a sheet of 2mm plywood coated with mastic and grease, braced against the hull; then the same sheet fastened to the hull with self-tapping screws. With the repair in place, we removed the mat to see how well it worked. At sea, there would be no obvious reason to remove it but unless you get a tight seal at the sheet's leading edge, it's unlikely to last long once you get some way on. Covering the plastic sheet with a fothered sail would protect it from the seaway, improving its durability.

DIY collision mat Did we need a more permanent repair? We wanted to test whether the DIY mat remained watertight under way. With neither engine nor mast, we asked the travel hoist crew to run the boat ahead and astern in the slings. The mat leaked badly, but it wasn't a good fother on this occasion and leaked whether moving or not. so I'm not sure we learned anything useful in this test. If you can't get at the hole from inside the hull, you will have no choice but to get this right, and it is possible.



ABOVE: Get the mat right and you can stop water coming in completely. INSET: Our second mat didn't work as well and leaked when we moved



Bracing seems an obvious solution but in practice we struggled to make it work

Braced board and cushion

It was difficult to shape the cushion to the hole. A thinner pillow worked better, but we didn't have a bracing board small enough for the tiny orange pillow. Nor could we find a brace strong enough to exert sufficient pressure. The deck broom was about to break so we used the boathook, which did break. We could have sawn the spinnaker pole, but to what exact length? Could we deploy it in such a confined space? Given plenty of time, it would have worked but we timed it out to try other methods.



Two items hose-clipped together make an adjustable brace



We put grease round the hole and a ring of mastic on the board

Braced, bonded board

We slapped half a tub of Ramonol marine grease around the hole and squeezed a ring of fast-curing mastic onto one side of a 2mm marine plywood board. The plan was to brace this board over the hole using a cushion and bracing



Bad bracing and poor curing conditions scuppered this idea

board, with the grease making a quick seal while the mastic cured to provide a more lasting seal. Unfortunately, due to the bracing problems described, we never exerted the pressure required, the leak never stopped and the mastic never cured. Solve the bracing issue and this might work.





We tried nailing the same 2mm ply board in place, still covered in grease and mastic, but it was impossible to penetrate the hull. Self-tappers were also fruitless. We used a double-pinion hand drill because an electric one underwater wouldn't work. Despite breaking a drill bit, we made five holes and, using self-tappers, screwed a 2mm ply board over the hole. It worked well. Despite the grease, the board was beginning to 'sweat' after five minutes, so thicker ply, but still flexible, would be better.





ABOVE: Drilling holes in the hull wasn't easy with a hand drill but we eventually managed it. LEFT: Self-tappers held the board well but water was beginning to 'sweat' through it



Scoop out and mix the two parts of epoxy using the wooden paddle

Epoxy repair kit

The Kollision Kit is an underwater repair kit with a two-pack epoxy bonding system promising rapid cure. Having keyed the surface

with the wet-and-dry sandpaper supplied, I cut the mat to fit, mixed the two epoxy parts, spread the epoxy on the polymat and placed it over the hole. Having braced it in place for five minutes, it created a very decent repair. Under time pressure, I couldn't mix all the epoxy, as it was difficult to spoon out of the pots, so I didn't get the coverage I needed and, after a couple of minutes, a small leak appeared. In general, though malodorous and messy, it was very easy to apply. **Price** £71 **Contact** Epoxy Solutions **Tel** 01454 612445 **Website** www.epoxysolutions.co.uk



Smear the mixed epoxy on the furry side of the polymat supplied



Then, with the fother in place, place the mat over the hole



Brace the repair against the hull for five minutes while the epoxy cures

Is it possible to save your boat if she's holed? Find out on the next page 🚽



What we learned

You can save your boat

Being holed below the waterline presents a number of problems in a variety of scenarios, depending on the size and location of the hole, but you can almost certainly save your boat. During this test, a very clear action plan emerged and, with a few inexpensive, multipurpose preparations such as the DIY collision mat and Strong Grips.

'There's every reason to suggest that not only can you keep her afloat, you could even bail her dry'

the hand drill, some self-tappers, and the Kollision Kit, which can also be used for other repairs. there's every reason to suggest that not only can you keep her afloat, you could even bail her dry.

The quickest fix

Stamping a pillow over the hole takes a fraction of a second and stems the flooding very well. It would be my first response, to buy time. Cushions are too resistant to shaping, as are sailbags, so I'd choose a small pillow every time. If you can brace the pillow in place, you'll be free to move around, but we struggled to make bracing work. If you can't get at the hole, move straight to the next step and get a sail or collision mat in place.

We used a damp course with Strong Grips and mousing twine to haul it into place. On reflection, I'd use a thicker line because the sheet needs to be taut, mousing twine cuts into the hands and is difficult to tie securely. We saw Strong Grips at Southampton Boat Show a couple of years ago. They're supposed to be used for holding awnings and covers in place, but I thought they'd be ideal for this purpose. A waterproof tarpaulin would work instead of damp course, and it would have cringles already fitted.

If you're holed either side of a fin keel, or you have a longkeeler, you'll need to position the sheet on the damaged side of the centreline. Tie off the fore and aft upper lines to the toerail at a diagonal angle. With a fin-keeler,

run the lower lines under the bow and stern, using a boathook to poke the aft line under the rudder and secure them on the opposite toerail. If you have a long-keeler, run the aft line under the counter and up to the opposite stern fairlead and the forward line

under the bow and up to the opposite fairlead, and tie both off. Water pressure should take care of the rest, but be ready to seesaw the sheet into place and check below to see if it's working.

Specialist kit

Our plan was to only use kit that you might find on the average cruising yacht. By and large, we managed to stick to that. One exception was the hand drill. We were lifting and draining the boat before the internal water level rose above the hole so that we could see the water gushing in and assess the effectiveness of each



With a good fother in place, the Kollision Kit made a sound repair

It may not look much, but...

Flow rate mathematics is quite complicated but the estimates I found suggest that a 5cm (2in) hole 30cm (1ft) below the waterline will leak 300 litres (66 gallons) per minute. A 10cm (4in) hole at the same depth leaks 1,100 litres (242 gallons) per minute, enough to sink a 30ft

yacht in 12 minutes.



Panic tends to rise with the water level but it's important to think clearly

repair. At sea that's not an option and it's likely you'll be working underwater, so an electric drill won't work. Hammering is futile, so we spent £5.95 on a hand drill. It wasn't especially easy to use, but we succeeded eventually.

The other exception was the epoxy repair kit. We had the perfect opportunity to test the Kollision Kit. It comes in a plastic case from Epoxy Solutions, a UK company. The Royal Marines, among others, use the kit to repair beach-damaged RIB hulls. It's intended for external application, but I would never recommend readers leap overboard. Applying the required pressure around the repair outside would also be problematic. It can't be used if

This small hole



We had an 8cm (3in) hole 20cm (8in) below the waterline. It may not have looked too threatening but in

the first 7-8 minutes of the test, of which maybe 30 seconds was spent with nothing over the hole, displacement increased by 2,000kg, suggesting 2,000 litres (440 gallons) had leaked in, and the water was 5cm (2in) above the sole and 20cm (8in) above the bilge. When holed, response speed is of the essence.

water is flooding in, but as the collision mat had worked so well, reducing flow to almost nothing, we thought it was worth a shot.

Two tips: The rubber gloves supplied took ages to haul on. finger by finger. Use washing-up gloves instead. Secondly, the two epoxy parts ought to be supplied in tubes or syringes. With the adrenalin pumping, I wasn't keen to fiddle around with the wooden paddles that were supplied, spooning out every last bit of epoxy. Unfortunately, when spreading it onto the polymat, I didn't have enough to cover the edges completely and that's where the leak appeared. My mistake but I'm sure it wouldn't be an uncommon one. 🛦

